

No. 55 of 2008

1 October 2008

Dear Port Users and Staffs

VEHICLES WITH ENGINE RUNNING LEFT UNATTENDED

- 1 It has been observed that there is an unsafe practice by the forklift operators and vehicles drivers who leave their engines running when they are not in the operating cabin and around the vicinity of the forklifts and vehicles. This unsafe practice may lead to serious accidents involving injuries and property damages.
- 2 The potential hazards for these unsafe practices are:
 - a. Accidental activation of the control level of forklift when alighting/boarding the cabin.
 - b. Unauthorized personnel operating the vehicle when the driver/operator is not around the vicinity of the vehicle.
 - c. Runaway vehicles when the parking brake is not properly engaged or faulty.
- 3 All drivers/operators should switch off the engines before alighting from their operating cabin in order to eliminate the above hazards.
- 4 Please ensure the compliance of the above requirements with immediate effect.
- 5 If you need more clarifications, please contact:-
 - i. David Ng at 66609503 or email: davidng@jp.com.sg or
 - ii. Ivan Tan at 66609732 or email: ivantan@jp.com.sg or
 - iii. FSS duty officer at 66609552 or email: jpfss@jp.com.sg

Thank You.

Adrian NG
Fire & Safety Department
FOR JURONG PORT PTE LTD